

Arizona Department of Transportation
Yuma District
March 27, 2007

Route		MP	Str. No.	Str. Name	Year Built	Mat.	Des.	Deck Area	Deficiency Classification	Sufficiency Rating
8	B	0.01	486	Colorado River Br	1956	4	02	57753	F	60.52
8		110.35	1505	Wash Bridge SFR	1923	1	01	1232	F	76.74
8	B	119.76	444	Sand Tank Wash Br	1928	2	01	8262	F	63.56
10		0.01	619	Ehrenberg Bridge	1960	3	02	115529	S	67.72
10		17.50	826	West Quartzsite TI UP	1964	4	02	7731	F	74.35
95		38.00	343	Wellton Mohawk Canal Bridge	1950	2	04	3074	F	57.80
95	S	144.83	191	Colorado River Br	1937	3	02	19549	S	24.98

Material

<u>Code</u>	<u>Description</u>
1	Concrete
2	Concrete Continuous
3	Steel
4	Steel Continuous
5	Prestressed Concrete
6	Prestressed Concrete Continuous
7	Timber
8	Masonry
9	Aluminum, W.I. or C.I.

Design

<u>Code</u>	<u>Description</u>
01	Slab
02	Stringer/Multibeam or Girders
03	Girders and Floorbeam System
04	Tee Beam
05	Box Girders – Multiple Precast
06	Box Girders – Cast-in-Place
07	Frame
08	Orthotropic
09	Truss – Deck
10	Truss – Thru and Pony
11	Arch – Deck
19	Culvert

F – Functionally Obsolete
S – Structurally Deficient