Arizona Department of Transportation
Tucson District
March 27, 2007

Route		MP	Str. No.	Str. Name	Year Built	Mat.	Des.	Deck Area	Deficiency Classification	Sufficiency Rating
8		157.55	1068	Smith Road OP EB	1962	2	01	3888	F	79.72
8		157.55	1069	Smith Road OP WB	1962	2	01	3888	F	79.72
10		175.81	1214	Casa Blanca TI UP	1967	4	02	10490	F	77.52
10		185.26	1151	Hwy 387 TI UP	1967	4	02	10102	F	65.49
10		208.79	945	Sunshine Blvd TI UP	1965	4	02	9750	F	79.00
10		264.37	1219	Palo Verde TI OP EB	1965	4	02	9165	F	77.00
10		273.14	711	Rita Road TI UP	1962	4	02	8236	F	61.43
10		275.49	713	Houghton Rd TI UP	1962	4	02	8236	F	71.51
10		279.37	744	Vail Rd TI UP EB	1962	4	02	5632	F	68.54
10		279.37	745	Vail Rd TI UP WB	1962	4	02	5264	F	56.76
19		5.30	1302	Potrero TI SB Ramp UP	1969	1	06	3374	S	67.32
19		56.94	1547	Santa Cruz SB on Ramp	1956	4	02	13514	F	77.55
19		59.90	1120	Drexel Road UP	1965	4	02	9625	F	72.52
77		109.15	499	San Manuel OP	1957	3	02	4320	F	78.96
77		123.52	399	Aravaipa Creek Br	1953	4	02	11116	F	69.39
82		5.67	424	Santa Cruz River Br	1955	4	02	10500	F	57.03
84		195.75	90	Picacho SPRR OP EB	1932	1	04	3686	F	57.32
86		144.79	200	Wash Bridge	1938	2	01	1726	F	59.75
86		145.22	4615	RCB	1938	2	19	864	F	74.15
86		145.93	4616	RCB	1938	2	19	896	F	74.15
86		147.04	4617	RCB	1938	2	19	1161	F	74.15

Material

Code	Description
1	Concrete
2	Concrete Continuous
3	Steel
4	Steel Continuous
5	Prestressed Concrete
6	Prestressed Concrete Continuous
7	Timber
8	Masonry
9	Aluminum, W.I. or C.I.

F – Functionally Obsolete
S – Structurally Deficient

Design

Code	Description
01	Slab
02	Stringer/Multibeam or Girders
03	Girders and Floorbeam System
04	Tee Beam
05	Box Girders – Multiple Precast
06	Box Girders – Cast-in-Place
07	Frame
08	Orthotropic
09	Truss – Deck
10	Truss – Thru and Pony
11	Arch – Deck
19	Culvert