

**Arizona Department of Transportation  
Flagstaff District  
March 27, 2007**

Route		MP	Str. No.	Str. Name	Year Built	Mat.	Des.	Deck Area	Deficiency Classification	Sufficiency Rating
15		22.55	1236	Virgin River Br # 7	1967	4	02	32240	S	24.00
17		340.02	1264	I 40 TI OP WB	1966	2	06	9841	F	77.00
40	B	196.08	295	Rio De Flag Bridge	1934	2	01	3877	S	41.50
40	B	200.54	1184	E Flag ATSF + Hwy UP	1967	4	02	29599	F	71.11
40		224.70	321	Babbitts Tank Br EB	1949	2	01	3568	S	48.89
89	A	375.66	232	Midgely/Wilson Canyon Bridge	1938	4	11	10173	F	62.89
89	A	387.35	79	Pumphouse Wash Br	1931	3	02	5056	F	58.61
89		466.88	532	Cameron Bridge	1959	4	09	24990	S	67.37
89	T	467.16	1049	Cameron Low Level Br	1958	4	02	3106	F	64.00
89		471.43	697	Five Mile Wash Br	1962	2	01	5738	F	67.35
89		481.89	582	Wash Bridge	1960	2	01	4973	S	48.50
160		349.90	1011	Begashbito Wash Br	1956	1	04	3080	F	50.76
179		302.50	736	Dry Beaver Creek Br	1962	4	02	5843	F	62.79

**Material**

<u>Code</u>	<u>Description</u>
1	Concrete
2	Concrete Continuous
3	Steel
4	Steel Continuous
5	Prestressed Concrete
6	Prestressed Concrete Continuous
7	Timber
8	Masonry
9	Aluminum, W.I. or C.I.

**Design**

<u>Code</u>	<u>Description</u>
01	Slab
02	Stringer/Multibeam or Girders
03	Girders and Floorbeam System
04	Tee Beam
05	Box Girders - Multiple Precast
06	Box Girders - Cast-in-Place
07	Frame
08	Orthotropic
09	Truss - Deck
10	Truss - Thru and Pony
11	Arch - Deck
19	Culvert

**F** - Functionally Obsolete

**S** - Structurally Deficient