

Arizona Department of Transportation
Prescott District
March 27, 2007

Route	MP	Str. No.	Str. Name	Year Built	Mat.	Des.	Deck Area	Deficiency Classification	Sufficiency Rating
17	238.60	339	Moores Gulch Br SB	1950	4	02	6230	F	70.39
17	239.20	968	Lit Squaw Crk Br NB	1967	4	02	11214	S	72.71
17	239.55	340	Lit Squaw Crk Br SB	1950	4	02	6229	S	56.39
17	293.40	654	Dry Beaver Crk Br SB	1961	4	02	7533	S	69.90
60	110.24	535	Washington St UP Wickn	1937	2	07	2042	F	71.76
60	110.26	1000	Wick Frontier St UP	1937	2	07	1928	F	74.45
60	110.53	161	Hassayampa River WB	1936	3	02	15248	F	62.41
60	110.53	737	Hassayampa River EB	1962	4	02	17630	S	47.27
69	296.26	385	Hwy 89 TI Whipple OP	1952	4	02	7780	S	65.01
87	257.92	456	East Verde River Br	1955	4	02	7140	F	62.88
89	313.37	1042	Granite Creek Br SB	1956	4	02	7680	S	77.70
89	333.09	964	Del Rio Ranch Bridge	1967	2	01	6054	F	56.87
169	0.25	1371	Agua Fria River Br	1969	2	04	5563	S	52.67
260	209.88	758	Black Canyon Wash Br	1963	4	02	6550	F	65.67

Material

<u>Code</u>	<u>Description</u>
1	Concrete
2	Concrete Continuous
3	Steel
4	Steel Continuous
5	Prestressed Concrete
6	Prestressed Concrete Continuous
7	Timber
8	Masonry
9	Aluminum, W.I. or C.I.

Design

<u>Code</u>	<u>Description</u>
01	Slab
02	Stringer/Multibeam or Girders
03	Girders and Floorbeam System
04	Tee Beam
05	Box Girders - Multiple Precast
06	Box Girders - Cast-in-Place
07	Frame
08	Orthotropic
09	Truss - Deck
10	Truss - Thru and Pony
11	Arch - Deck
19	Culvert

F - Functionally Obsolete
S - Structurally Deficient