

**Arizona Department of Transportation**  
**Kingman District**  
**March 27, 2007**

Route	MP	Str. No.	Str. Name	Year Built	Mat.	Des.	Deck Area	Deficiency Classification	Sufficiency Rating
40	0.55	921	SR 95 TI UP (Topock)	1966	3	02	6496	F	74.95
40	21.01	363	Flat Top Wash Br EB	1967	2	01	5668	S	67.10
40	40.42	1658	Griffith Wash Br WB	1974	2	01	6289	S	67.18
40	53.55	1358	E Kingman TI OP WB	1969	2	06	9649	F	79.00
40	71.99	1082	Hwy 93 TI UP	1963	4	02	10189	F	77.00
66	80.10	738	Hackberry Wash Br	1962	4	02	12461	F	65.99
68	0.00	2539	Laughlin Br-Colo Rvr	1987	5	02	39209	F	74.01
93	97.50	492	Kabba Wash Br NB	1958	2	01	4695	F	57.18
93	165.54	548	Big Jim Wash Bridge	1959	2	01	7070	F	49.34
95	182.38	1824	McCulloch Blvd UP	1977	5	06	6976	F	79.22
95	226.07	2435	Needles Bridge	1978	6	02	27451	S	69.96

**Material**

<u>Code</u>	<u>Description</u>
1	Concrete
2	Concrete Continuous
3	Steel
4	Steel Continuous
5	Prestressed Concrete
6	Prestressed Concrete Continuous
7	Timber
8	Masonry
9	Aluminum, W.I. or C.I.

**Design**

<u>Code</u>	<u>Description</u>
01	Slab
02	Stringer/Multibeam or Girders
03	Girders and Floorbeam System
04	Tee Beam
05	Box Girders – Multiple Precast
06	Box Girders – Cast-in-Place
07	Frame
08	Orthotropic
09	Truss – Deck
10	Truss – Thru and Pony
11	Arch – Deck
19	Culvert

**F** – Functionally Obsolete  
**S** – Structurally Deficient